

# **Laboratory Manual**

**Subject Code: PCME-304**

**Subject Name: CAD/CAM**

**ICD Programme**



**Developed By**

**Dr. Sunil Kumar, AsP (ME)**

**DEPARTMENT OF MECHANICAL ENGINEERING  
SANT LONGOWAL INSTITUTE OF ENGINEERING AND TECHNOLOGY  
(Deemed to be University) LONGOWAL-148106, (PUNJAB)**

Title of the course : **CDA/CAM Lab**  
 Subject Code : PCME-304  
 Weekly load : 2 LTP 0-0-2  
 Credit : 1

**COURSE OUTCOMES:**

After successful completion of course, the students should be able to

CO1: Enhance the knowledge of application of CAD software in drawing and modeling

CO2: To understand the fundamentals of CNC machines, additive manufacturing and industrial robots

CO3: Obtain knowledge, understand implementation of CNC programming

Pre-requisite knowledge:

Cos	Programme Outcomes (POs)								
	PO1	PO2	PO3	PO4	PO5	PO6	PO7	PSO1	PSO2
CO1	3	3	3	2	3	3	3	3	3
CO2	3	3	3	2	1	3	3	3	2
CO3	3	1	2	3	1	2	2	2	3
Avg.	3	2.3	2.7	2.4	1.7	2.7	2.7	2.7	2.7

**List of Experiments:**

S. No.	Title
1.	Introduction to AutoCAD.
2.	Draw the 2D drawings of components using line command and write the procedure.
3.	Draw the 2D drawings of components using line command and write procedure of the same.
4.	Draw the 2D drawing of the given parts using appropriate modify commands.
5.	Draw the 2D drawing of the given parts using appropriate modify commands.
6.	Draw front view full section and top view of the given drawings.
7.	To study about the general instruction of CAD/CAM lab and safety precautions of CNC both lathe and milling machine.
8.	To study the constructional details of CNC lathe machine.
9.	To study the lathe bed & slide ways.
10.	To study the construction and working of (a) Automatic Tool changer (b) Pallets
11.	To study the constructional details of CNC milling machine.
12.	Write a program of turning / step turning using G-codes M-codes for a given job on CNC lathe machine.
13.	Write a program for threading operation using G& M-codes on lathe machine of a given job.
14.	Write a program of CNC milling machine using G-codes M-codes for a given job on CNC milling machine

## **GENERAL INSTRUCTION**

1. All the students are instructed to wear protective uniform, Shoes and identity card before entering into the laboratory.
2. Before starting the exercise, students should have a clear idea about the principal of that exercise.
3. All the students are advised to come with completed record and corrected observation book of pervious experiment.
4. Do not operate any computer/instrument/machine without getting staff member's prior permission.
5. The entire instrument is costly. Hence handle them carefully, to avoid fine for any breakage.
6. Utmost care must be taken to avert any possible injury while on Laboratory work. In case, anything occurs immediately to the staff members.
7. Shutdown the computer in the right way at the end of Laboratory work.
8. One student from each batch should put his/her signature during receiving the instrument in instrument issue Register.

## EXPERIMENT No.1

**Aim:** Introduction to AutoCAD

**Requirements:** 1) PC/Laptop 2)AutoCAD

**Objective:** Introduction to fundamentals of AutoCAD, familiarizing students with the user interface of AutoCAD and frequently used commands.

### **Introduction:**

AutoCAD is a CAD (Computer Aided Design or Computer Aided Drafting) software application for 2D and 3D design and drafting, developed and sold by Autodesk, Inc. Initially released in late 1982, AutoCAD was one of the first CAD programs to run on personal computers, and notably the IBM PC. Most CAD software at the time ran on graphics terminals connected to mainframe computers or mini-computers.

In earlier releases, AutoCAD used primitive entities — such as lines, polylines, circles, arcs, and text — as the foundation for more complex objects. Since the mid-1990s, AutoCAD has supported custom objects through its C++ API. Modern AutoCAD includes a full set of basic solid modeling and 3D tools. With the release of AutoCAD 2007 came improved 3D modeling functionality, which meant better navigation when working in 3D. Moreover, it became easier to edit 3D models. The mental ray engine was included in rendering, it was now possible to do quality renderings. AutoCAD 2010 introduced parametric functionality and mesh modeling.


Figure 1.1 shows a typical initial AutoCAD windows screen. The top line displays the Windows pull down menus for exiting a program and changing a program.

The second line is the standard toolbar and contains a group of mostly used commands.

The third line contains some command icons and an area that shows the current docked, object properties that are active.


The bottom left corner of the screen shows the coordinate display position of horizontal, vertical crosshairs in terms of an X, Y coordinate value whose origin is lower left corner of the drawing screen.

## Graphics user interface




## Frequently used toolbars

### 1. Draw



## 2. Modify



## 3. Standard

## 4. Dimension

## 5. Properties

### **Methods of coordinate input of a point:**

ABSOLUTE CO-ORDINATES –

RELATIVE CO-ORDINATES –

POLAR CO-ORDINATES –

Brief Procedure of drawing

1. Define the drawing limits
2. ZOOM ALL
3. Define units
4. Start Drawing
5. Dimensioning
6. Title block
7. Save, print and export


## EXPERIMENT No. 2

**Aim:** Draw the 2D drawings of components using line command and write the procedure.

**Requirements:** 1) PC/Laptop 2) AutoCAD


**Objective.** Introduction to basic commands and different modes to enter the coordinates of point to draw a part.

### Lab exercise:




Exercise 2.1 (INCHES)


### Drawings for Practice



Exercise 2.2 (MILLIMETERS)



Exercise 2.3 (MILLIMETERS)



Exercise 2.4 (INCHES)



### EXPERIMENT No. 3


**Aim:** Draw the 2D drawings of components using line command and write procedure of the same.

**Requirements:** 1) PC/Laptop 2) AutoCAD

**Objective.** Introduction to basic commands and polar mode to enter the coordinates of a point to draw a part.

#### Lab exercise:


AB=5.0000  
BC=1.9526  
CD=2.3049  
DE=1.8039  
EF=3.2500  
FG=4.1003  
Find the length of AG



Exercise 3.1 (INCHES)

#### Drawing for practice

AB=65.7007  
BC=50.0000  
CD=64.0312  
DE=50.0000  
EF=42.4264  
FG=64.0312  
GH=76.1577  
Find the length of AH



Exercise 3.2 (MILLIMETERS)


## EXPERIMENT No. 4

**Aim:** Draw the 2D drawing of the given parts using appropriate modify commands.

**Requirements:** 1) PC/Laptop 2) AutoCAD


**Objective.**

**Lab exercise:**



Exercise 4.1 (MILLIMETERS)

**Drawing for practice**



Exercise 4.2 (INCHES)


## EXPERIMENT No. 5

**Aim:** Draw the 2D drawing of the given parts using appropriate modify commands.

**Requirements:** 1) PC/Laptop 2) AutoCAD


**Objective.**

**Lab exercise:**



Exercise 5.1 (MILLIMETERS)

**Drawing for practice**



## EXPERIMENT No. 6


**Aim:** Draw front view full section and top view of the given drawings

**Requirements:** 1) PC/Laptop 2) AutoCAD

**Objective.** Introduction to the sectioning in AutoCAD and enhancing the proficiency of the students in the same.


**Lab exercise:**

Assume missing dimensions.



Exercise 6.1(MILLIMETERS)

**Drawing for practice**



Exercise 6.2 (INCHES)

## EXPERIMENT No. 7

**Aim:** : To study about the general instruction of CAD/CAM lab and safety precautions of CNC both lathe and milling machine.

**Requirements:**

**Objective.**

**Safety precautions...** CNC machines has safety device fitted to protect the machines and operation from unexpected accident. These safety precautions are as follows.....

**1. Tidyness...**

- Do not place object on or around the machines so that it interface with the quarts or the operations of the machines.

**2. Power source...**

- Ensures the correct cable for the power source is used.
- When power fails turn off the isolators.
- Ensure the machine is switched on before its maintenance is carried out.

**3. Lubrication ...**

- For lubrication please refers to the chart in maintenance section.
- Checks state of slide ways lubrication each day.

**4. Recommendation on safety precautions ...**

Always wears clothing that is suitable for opening the machines. Secure the work piece cleaning. Only operate the machines with safety quarts. Do not open the safety quarts during operation it is very dangerous to touch any rotating point. Never attempt to remove the scarf while the machine is turning. After setting tools, perform trail cut using manual operation. Remember to use tool offset to avoid machining errors. Never clean the machine or attachment while machine is running. Do not operate the machines with the electrical control box open. Turn the isolator to off before opening the electrical cabinet. When an emergency stop is required stop key on the operation panel. This cut power to the spindle and the axis driven reset by inserting key and turning the power on.

**General instruction of CAD/CAM lab...**

- Switch on to start the computer.
- Log on the computer and than enter the password.
- Do not use pen drive in the lab without permission.
- Do not delete copy any file without permission.
- Do not load any software in pc, please contact concerned faculty, staff to rectify it, if you have problem.
- Rough handling of hardware/equipment is strictly prohibited.
- Maintains decorum of lab while working.
- Shut down the computer properly after working.
- Keeps the chairs at their proper place while leaving lab....


## EXPERIMENT No. 8

**Aim:** : To study the constructional details of CNC lathe machine.

**Requirements:** CNC lathe machine.

**Objective.** Machine structure, Slide ways, drive units (spindle drive, axis drive) specification of CNC lathe

**Theory :** Design of a conventional machine tool is not suitable for CNC machines. Many design changes are required for CNC machines as compared to their conventional counterparts, due to a number of additional requirements which CNC machines are expected to meet. Axis drive motors in CNC machines replace the manual hand wheel controls in the conventional machine.



**1. MACHINE STRUCTURE:** The design and construction of CNC machine should be such that it meets the following main objectives:

- a) High precision and repeatability
- b) Reliability
- c) Efficiency

**2. SLIDEWAYS:** In the conventional machine tools, there is direct metal-to-metal contact between the slide ways and the moving slide.

The design of slide ways in a CNC machine should be:

- 1) Reduce friction
- 2) Reduce wear
- 3) Satisfy the requirements of movements of the slides.
- 4) Improve smoothness of the drive.

**3. DRIVE UNIT:** The drive unit are require to perform following functions:

- To drive the main spindle (SPINDLE DRIVE)
- To drive the saddle or carriage (AXIS DRIVE)

### SPECIFICATION OF CNC LATHE

Standard features- star turn

Machine dimension list

Length: 600mm

Width: 425mm

Height: 430mm

Capacity

Distance between centers: 250mm

Swing over cross slide : 38mm

Swing over bed : 140mm

Spindle taper number : 1 MT

Spindle bore : 10mm

X-Axis ball screw : 8mm x 2.5mm pitch

Z-Axis travel : 10mm x 4mm pitch

Bed : ground

Main spindle:

Drive motor : 0.5 HP Dc permanent magnet

Spindle nose : threaded type

Spindle bore : 10mm

Saddle:

Axis motor : stepper motor 200 steps/ rev.

Optional indexing turret:

Turret lead type : Drum

No. Of tool stations : 8

Tool size square : 12mm x 12mm

Round : 19mm dia.

*NOTE: max. Turning diameter May be limited due to tooling*

*Machine work light : 110v ac*

*Power supply : 1 PH 240v*

*Total power connected : 8A / phase*

**OPTIONAL FEATURES:**

A) *Pneumatic chuck*

B) *Spray mist coolant*

## EXPERIMENT No. 9

**Aim:** To study the lathe bed & slide ways

**Requirements:**

**Objective..**

**Introduction:**

In the conventional machine tools, there is direct metal to metal contact between the slide ways and the moving slide. Slide movement are very slow and machine utilization is also low .this arrangement is adequate for conventional machine tools. the demand on slide ways is much more in CNC machine because of rapid movement and higher machine utilization. The conventional type if arrangement with metal to metal contact does not meet the requirements of numerically control machine tools. The design of slide ways in a CNC machine should be:

- 1) Reduce friction
- 2) Reduce wear
- 3) Satisfy the requirements of movements of the slides.
- 4) Improve smoothness of the drive

To meet these requirements in CNC Machine tool slide ways, the technique used include hydrostatic slides, linear bearings with balls, rollers or needles and surface coating.

**HYDOSTATIC SLISEWAYS:**

In hydrostatic slide ways, air or oil is pumped in to small pocket or cavities machined into the carriage or slides which are in contact with the sideways. the pressure of the fluid gradually reduces to atmospheric pressure as it keeps out from the pockets through the gap between the slides and slide ways. the hydrostatic slides provides almost a frictionless condition for movement of slide. For efficient operation, it is very important that the fluids and slide ways are kept clean. Also, hydrostatic slide ways need a very large surface and to provide adequate support.

**LINEAR BEARING WITH BALL, AND ROLLERS:**

The sliding friction due to direct metal to metal contact, between the slides and slide ways is replaced with rolling friction by the use of antifriction ball or roller bearing. These are designed to run along precision ground shaft and offer frictionless movement over varying strokes of length with high linear precision. for movement along a flat plane, recirculation linear roll bearings are used. The main characteristic of linear roller bearing is that there is continuous roller circulation which allows unlimited linear movement. The linear roller bearing is also called tychoway ,consist of hardened and precision ground supporting element with very close tolerance. the rollers are in contact with guide ways machined on bed of machine. This arrangement provides smooth and easy movement.

**CONSTRUCTION OF BED:**

In CNC machine bed in general may be considered to be an assembly of the following components.

- #. Structure
- #.. Drives {including power units}.
- #.. Actuation system
- #.. Tool and work handling devices.
- #.. Controller units



## EXPERIMENT No. 10

**Aim:** : To study the construction details and working of

(a) Automatic Tool changer

(b) Pallets

(c) **Requirements:** Automatic Tool changer, Pallets

**Objective.** Familiar with ATC and Pallets.

### Automatic tool changer:

It is an essential component of all NC/CNC machines. All the machines are capable of holding multiple tools. In the case of lathe machine they are all mounted on a turret when the operation of one tool ends, the turret moves away from the spindle. It indexes and automatically brings the next tool to lead position. A motor power turret gear mechanism is used for indexing the turret. Machine controller gives all signals to the motor that runs the wheel on it.


Accuracy of NC machine tool could be improved by the following ways.

- (1) Rigidity of bed.
- (2) Accurate control slide movement.
- (3) Minimize the vibration.

If a milling machine has a long bed and while cutting at one of the edges, the outer edge which is not supported may cause deflection of the bed and hence we may not get the required accuracy. This phenomenon is explained in the figure. The phenomenon has happened because of the weight of the unsupported edge of the table while taking a cut on the work piece because of forces. It will have an effect on the dimensional accuracy of the work piece so the machine structure and its assembly should be designed to ensure that such deflection does not occur.

### Automatic pallet changer:

Saving time can be achieved by minimizing or even eliminating the time the machine centre stands idle during the individual setting of each unmachined component. With this objective, the machines could be provided with more than one table. While machining is being performed on the work part, the operation could be unloading the complete piece or setting up the next one on another table called a pallet shuttle system.



## EXPERIMENT No. 11

**Aim:** : To study the constructional details of CNC milling machine.

**Requirements:** CNC milling machine.

**Objective.** Familiar with CNC milling machine.

**Theory :** Design of a conventional machine tool is not suitable for CNC machines. Many design changes are required for CNC machines as compared to their conventional counterparts, due to a number of additional requirements which CNC machines are expected to meet. Axis drive motors in CNC machines replace the manual hand wheel controls in the conventional machine.



### MACHINE SPECIFICATION

#### A) CABINET:-

Length: -	550mm
Width: -	540mm
Vertical length: -	880mm

#### B) CAPACITY:-

Maximum cross travel: -	90mm
Maximum longitudinal travel	170mm
Maximum head travel: -	115mm
Spindle nose to table top: -	190mm
Spindle to column: -	110mm
Spindle taper: -	R8mm
Spindle tapes for ATC	BT35
Working table surface	360mmX130mm
3tee slots: -	10mm width X50mm centre
Z-axis ball screw	16dia.X 5pitchmm
X-axis ball screw: -	16d X 5p mm
Y-axis ball screw: -	.01mm
Weight: -	110kg without ATC
Weight: -	113 kg with ATC

#### C) ENVIRONMENTAL CONDITION:-


Power supply: -	220/240V, 8A 50/60 HZ single phase.
-----------------	-------------------------------------

## EXPERIMENT No.12

**Aim:** Write a program of turning / step turning using G-codes M-codes for a given job on CNC lathe machine.

**Requirements:** 1) PC/Laptop

**Objective.** CNC lathe program



Part Program


```
[BILLET X25 Z50
N10 G21 G40 G99
N20 G28 U0 W0
N30 M06 T01
N40 G97 S1500 M03
N50 G00 X23 Z5
N60 G01 Z-35 F0.1
N70 G00 X24
N80 G00 Z5
N90 G00 X21
N100 G01 Z-35 F0.1
N110 G00 X22
N120 G00 Z5
N130 G00 X19
N140 G01 Z-35 F0.1
N150 G00 X20
N160 G00 Z5
N170 G00 X17
N180 G01 Z-35 F0.1
N190 G00 X18
N200 G00 Z5
N210 G00 X15
N220 G01 Z-35 F0.1
N230 G28 U0 W0
N240 M30
```

## EXPERIMENT No.13

**Aim:** Write a program for threading operation using G& M-codes on lathe machine of a given job.

**Requirements:** 1) PC/Laptop

**Objective.** CNC lathe program



(Suppose Major Diameter 25mm, Minor 23 and Pitch is 2mm)

BOX type threading cycle G92

[BILLET X25 Z50

N10 G21 G40 G99

N20 G28 U0 W0

N30 M06 T01

N40 G97 S1500 M03

N50 G00 X25 Z5

N60 G92 X24.5 Z-50 F2

N70 G00 X25

N80 G00 Z5

N90 G92 X24 Z-50 F2

N100 G00 X25

N110 G00 Z5

N120 G92 X23.5 Z-50 F2

N130 G00 X25

N140 G00 Z5

N150 G92 X23 Z050 F2

G28 U0 W0


M30

### EXPERIMENT No.13

**Aim:** Write a program of CNC milling machine using G-codes M-codes for a given job on CNC milling machine.

**Requirements:** 1) PC/Laptop

**Objective.** CNC lathe program



Size of Billet : Length 80mm Width 80mm Thickness 10mm

Machining Required : Length 50x50

Part Program

```
[BILLET X80 Y80 Z10
```

```
[EDGE MOVE X0 Y0
```

```
[TOOLDEF T1 D06
```

```
N10 G91 G28 X0 Y0 Z0
```

```
N20 M06 T0101
```

```
N30 M03 S1500
```

```
N40 G90
```

```
N50 G00 X15 Y15 Z5
```

```
N60 G01 Z-1 F50
```

```
N70 X65
```

```
N80 X15 Y65
```

```
N90 Y15
```

```
N100 G00 Z10
```

```
N110 G91 G28 X0 Y0 Z0
```

```
M120 M30
```